

# STG, INC. DAILY REPORT

PROJECT NAME: Mooring Points Phase 3 - Kalskag

Pictures Taken Today? NO

FOREMAN: Paul Farmer

Temp/Weather: 50's

DATE: 8/28/2013

Precipitation: Rain off and on

## EQUIPMENT INFORMATION

EQUIPMENT DESCRIPTION	HOURS USED	FUEL PURCHASED	MAINTENANCE & COMMENTS
4-wheeler	10		
chainsaw	10		
pick-up truck	4		

## FREIGHT

CARRIER	DESCRIPTION

## SAFETY COMMENTS/CONCERNS

Chain saw safety, slips, trips and falls and watching for local traffic

## WORK NARRATIVE

Rented 4-wheeler and chain saw and pick-up truck and went over to Site Location 141, finished clearing brush and transported debris to dump.

Change In Site Conditions      Yes ☐      No ☐      If yes, provide description.

## EMPLOYEES & ACTIVITIES

NAME	HOURS	WORK DESCRIPTION/LOCATION
Paul Farmer	10	Clearing brush
Hant T. Alyosius	10	Clearing brush